Date:

Tuesday, 19/08/2008 4:04:18 PM

User:

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 41438 : 12306

Estimate Number P.O. Number

Julie Lecocq

This Issue

: NC Prsht Rev. First Issue

Previous Run

: // : 38679

: 19/08/2008

Type

S.O. No. :

: SMALL /MED FAB

Drawing Number

Project Number

Drawing Name

Part Number

: D269017 : D2690 REV. B2 : N/A

: B2

: LANYARD ASSEMBLY

Drawing Revision

Material

Due Date

: 02/09/2008

Qty:

20 Um:

Each

Written By

Checked & Approved By

Comment

Removed Manufacturer Release

SM/EC Certification

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0 CBL460

Loop Sleeve

Comment: Qty.:

2.0000 Each(s)/Unit

Total:

40.0000 Each(s)

Loop Sleeve

Pick: Qty

2

Part Number

CBL-460

Description Loop Sleeve

Batch

m 107234

540

Zo)

2.0

CBL1240

Comment: Qty : Total: 29.7360 f(s) 1.4868 f(s)/Unit

> Cable Pick:

Qty Part Number 17" CBL-1240

Description Cable

Batch m103927

SAD

08/09/16

25

3.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1

Comment: SMALL & MEDIUM FAB RESOURCE 1

Assemble as per Dwg D2690

4.0

QC5

INSPECT WORK TO CURRENT STEP

Comment: INSPECT WORK TO CURRENT STEP

5.0 PACKAGING 1



PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock Location:

Duit Moi Oopuoo Eta	Dart	Aeros	pace	Ltd
---------------------	-------------	-------	------	-----

W/O:			W	ORK ORDER CH	INGES					
DATE	STEP	PR	OCEDURE CHA					Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	•	PAR #:	Fault Cate	gorv:	NC NC	R: Yes	No DQ	\\ \:	Date:	
			,	J ,					_ Date: _	
NCR:		1	WORK ORD	ER NON-CONFO	RMANC	E (NCF	R)			
DATE	STEP	Description of NC	Corrective Action		Section B		Verific	Verification	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Descri Chief Eng	ption	Sign 8 Date	Section		Chief Eng	QC Inspector
									ļ	
								-		
				,						
	1						i		İ	1

NOTE: Date & initial all entries

Date:

Tuesday, 19/08/2008 4:04:18 PM

Usei:

Julie Lecocq

Customer: CU-DAR001 Dart Helicopters Services

Process Sheet

Drawing Name: LANYARD ASSEMBLY

Job Number: 41438

Part Number: D269017

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC21

FINAL INSPECTION/W/O RELEASE



08/17/9-MF 68-09-12

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



Dart Ae	rospace	Ltd								
W/O:			WC	RK ORDER CH	IANGES	• • • • • •				
DATE STEF		PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NC				_ Date: _ _ Date: _	
NCR:			WORK ORD	ER NON-CONFO	RMANCE					
DATE	STEP	Description of NC		Corrective Action	Section B		Verific	ation	Approval	Approval
	OIL.	Section A	Initial Chief Eng	Action Descri	btion	Sign & Date	Secti		Chief Eng	QC Inspector
						1	1			1


NOTE: Date & initial all entries



DESIG	M	ORAWN BY	DART AEROSPACE LTD VICTORIA INTERNATIONAL AIRPORT, CANADA
CHEC	KED_/	APPROVED	DRAWING NO. REV. B
D	nox	BW	D2690 SHEET 1 OF 1
DATE			TITLE SCALE
97.1	0.02		LANYARD ASSEMBLY NTS
 Α		97.07.03	NEW ISSUE
B		97 10 02	REVISED NOTE FOR ADDITIONAL LENGTH



	Α	97.07.03	NEW ISSUE
***************************************	В	97.10.02	REVISED NOTE FOR ADDITIONAL LENGTH
-	Bı	of or 01 08.20	ADD NOTE TO REMOVE 2.25" OF SLEEVE
	BZ	# 34.06.24	ADDED TOLERANCE



<u>D2690-X</u>

X = LENGTH IN INCHES

NOTE: CUT CABLE 2.50* INCHES LONGER THAN 'X' LENGTH.

FOLD ENDS TIGHT TO 'X' LENGTH AND CRIMP WITH SLEEVE AT END OF LOOSE END OF CABLE WITH

CBL-705 CRIMPING TOOL.

*ADDITIONAL LENGTH MAY BE NECESSARY IN

SOME APPLICATIONS. CUT AS REQUIRED.

RETURN TO ENGINEERING

UNCONTROLLED COPY

SHOP COPY

NOTE: IN SOME CASES, END HAS TO BE CRIMPED AFTER SUBJECT TO AMENIMENT WITHOUT NOTICE

ASSEMBLY WITH ATTACHING PARTS.

WORK DEPOR

. 1

NO.L

DEO's